



ДИРЕКТОРАТ
ЦИВИЛНОГ
ВАЗДУХОПЛОВСТВА
РЕПУБЛИКЕ СРБИЈЕ

ОПЕРАТИВНО ОБАВЕШТЕЊЕ <i>OPERATIONS ADVISORY MEMORANDUM</i>		OAM No: 3/2011 Датум издавања: 12.08.2011 <i>Issued on:</i>
Наслов: <i>Title:</i>	<i>Промена процедура инструменталног одласка, доласка и прилаза на аеродрому Никла Тесла Београд - LYBE</i>	

➤ *Увод*

Поштовани оператери,

С обзиром на објављени NOTAM у вези са радом VOR BEO, Агенција за контролу летења Србије и Црне Горе је израдила нове процедуре инструменталног доласка и прилаза на аеродром Никола Тесла као и процедуре инструменталног одласка са истог аеродрома.

Поступајући, у складу са новим процедурама инструменталног одласка, доласка и прилаза Јерпесен је урадио измене у својим публикацијама и објавио коа JEPPESEN NAVDATA ALERT.

➤ *Захтев ваздухопловних власти*

У прилогу обавештења достављамо свим оператерима JEPPESEN NAVDATA ALERT.

Потребно је да се сви оператери приликом одласка, доласка и слетања користе нове измењене процедуре.

Податке је могуће послати електронском поштом: jovanovicj@cad.gov.rs, на факс +381 11 311 7518 или као допис преко писарнице Директората.

Молимо да потврдите пријем овог обавештења
ДИРЕКТОРАТ ЦИВИЛНОГ ВАЗДУХОПЛОВСТВА
РЕПУБЛИКЕ СРБИЈЕ
ОДЕЉЕЊЕ САОБРАЋАЈНЕ ДЕЛАТНОСТИ



JEPPESEN[®]
NavData[®] Alert

!! URGENT !!

Date: 11 August 2011

Subject: Belgrade, Serbia
Nikola Tesla Airport (LYBE)
Belgrade [BEO] VOR
Multiple Arrival, Departure and Approach Procedures
Cycles 1108 and 1109

Changed Arrival, Departure and Approach Procedure information and Navaid unserviceable

Jeppesen NavData for cycle 1108 and 1109, effective 28 July 2011 and 25 August 2011 respectively, does not contain the updated information for multiple Arrival, Departure and Approach Procedures at Nikola Tesla Airport; Belgrade, Serbia (LYBE). Because of the Belgrade [BEO] VOR outage, AIP Supplement 1/11 was published on short notice. As a result, the changes contained therein are not available in cycle 1108 and could not be processed for the 25 August 2011 effective date (cycle 1109).

THEREFORE, DO NOT USE THE ARRIVAL, DEPARTURE AND APPROACH PROCEDURES LISTED ON THE FOLLOWING PAGES IN CYLES 1108 AND 1109 NAVDATA.

Revised coding will appear in Jeppesen NavData for cycle 1110, effective 22 SEP 2011. Until then an entry will appear in the NavData Change Notices beginning 19 Aug 11, and this Alert will be posted on the Jeppesen Web site

<http://www.jeppesen.com/main/corporate/company/alerts/aviation-alerts.jsp?region=Western%20Europe%20%26%20Mediterranean>

WE STRONGLY URGE YOU TO MAKE THIS INFORMATION AVAILABLE TO APPROPRIATE CREW MEMBERS OR CUSTOMERS IMMEDIATELY!

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

LYBE_1109

Standard Instrument Arrival Procedures - STAR

The following Standard Instrument Arrival Procedures (STAR) for Nikola Tesla Airport; Belgrade, Serbia (LYBE) are withdrawn and unusable in cycles 1108 and 1109 NavData:

STAR
BEO 4A [BEO4A]
BEO 5B [BEO5B]

Standard Instrument Departure Procedures - SID

The following Standard Instrument Departure Procedures (SID) for Nikola Tesla Airport; Belgrade, Serbia (LYBE) are unusable in cycles 1108 and 1109 NavData:

SID	Note:
BEOGRAD 4C [BEO4C]	Changed data
KOTUS 4C [KOTU4C]	Changed data
NERTA 2D [NERT2D]	Changed data
TISAK 4E [TISA4E]	Changed data
TOPOLA 3C [TPL3C]	Changed data
VALJEVO 2E [VAL2E]	Changed data
MITROVICA 2D [SMI2D]	Procedure withdrawn
MITROVICA 5E [SMI5E]	Procedure withdrawn
TADAM 2S [TADA2S]	Procedure withdrawn
TOPOLA 2D [TPL2D]	Procedure withdrawn
TOPOLA 2K [TPL2K]	Procedure withdrawn
VALJEVO 2D [VAL2D]	Procedure withdrawn
VALJEVO 2F [VAL2F]	Procedure withdrawn

The following new and temporary Standard Instrument Departure Procedures (SID) for Nikola Tesla Airport; Belgrade, Serbia (LYBE) are missing in cycles 1108 and 1109 NavData:

SID
TOPOLA 1Y [TPL1Y]
TADAM 1Y [TADA1Y]
MITROVICA 1Y [SMI1Y]
VALJEVO [VAL1Y]

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.

Terminal Approach Procedures

The following Terminal Approach Procedures for Nikola Tesla Airport; Belgrade, Serbia (LYBE) are unusable in cycles 1108 and 1109 NavData:

Terminal Approach Procedures
VOR DME Rwy 12 [D12]
VOR DME Rwy 30 [D30]
ILS DME Rwy 12 [I12]
ILS DME Rwy 30 [I30]

If you have questions concerning this NavData Alert, please contact Jeppesen Technical Support at:

Phone: 303-328-4445

E-mail: navdatatechsupport@jeppesen.com

NavData Alerts are published to advise users of significant issues in Jeppesen navigation data which may affect flight operations or safety. They are distributed to affected ARINC 424 NavData users (avionics companies and other raw data users) and airlines receiving NavData directly from Jeppesen. Alerts are not distributed by Jeppesen to individual airline, business aviation or general aviation pilots, but are available to them on the Jeppesen Web site, www.jeppesen.com. Different avionics equipment and computer systems use and display NavData and data derived from NavData differently. Avionics users should consult with their database update service provider for definitive information on whether their system is affected by this Alert.